






Urine-Monovette® Boric Acid

Patient User Guide

 <p>Remove stopper and keep for later use!</p> <p>Attach plastic straw.</p>	 <p>To avoid overfilling, Insert the plastic straw into the container and fill the Urine Monovette® up to the bottom of the label.</p>	 <p>To empty the plastic straw hold the Urine Monovette® in an upright position and pull the plunger backwards to the bottom of the tube.</p>	 <p>Remove the plastic straw, break off the plunger and throw away.</p> <p>Replace the stopper.</p>	 <p>Mix well after the sample collection (tilt approx. 5 time).</p>
--	--	---	--	--



Instructional Video:
Hygienic urine collection
with the Urine Monovette®